Field Service Bulletin No. 6

Order No.: DD+DIS104.01E

1 piece UMEAN MA1

ADC System Components

Type 4406

Rating			When?		
safety relevant	reliability	new function	as soon as possible	next service	as required
X			X		

Please file this document in section 13 of your technical documentation

StudyUID of an Examination combined with wrong Patient Data

This Field Service Bulletin replaces FSB No. 5 (DD+DIS039.01E)

The information given below is safety relevant as there maybe image data associated with wrong patient data.

Symptom

It may happen that the StudyUID of an examination is combined with wrong patient data, if the customer is working with a worklist from RIS. This bug may occur with all PRID versions released up to now (incl. PRID 1.2.07).

Defect

This may happen under the following circumstances:

The user selects a patient from the worklist. The selected data (including StudyUID if available from RIS) will be transferred to the ID-Screen. In case the user now presses the "New Patient" button, the patient data from the RIS will be overwritten, while the **StudyUID remains the one coming from the RIS**.
This occurs also if the user retrieves patient data from the "History List", from the "Patient List" or if he uses the "Recall" – button.

As a consequence, you may then have a combination of changed patient data together with the StudyUID from the RIS.

p.t.o.

printed in Germany 04 / 2001

Solution At the moment there is no solution for this problem. PRID 1.2.08 will fix that problem. It is currently under test and is supposed to be released in May 2001.

Measures

- It is a **must** to inform the customer about the problem.
- It is a **must** to inform the customer how he can avoid the problem:
  If the patient data were selected from the worklist, they must not be changed in the ID screen afterwards.
- It is a **must** to modify all systems in the field as soon as PRID 1.2.08 is available.